# Oregon Schools Seismic Feedback Form

## General information:

**1. Date of submittal**

September 27, 2012

**2. County**

Multnomah

**3. School district or special education district**

Multnomah County School District #40, David Douglas School District

**4. Name and title of person submitting report**

Patt Komar, Director of Administrative Services

**5. Year for reporting - Please submit separate forms for each year of reporting**

2007- 2012

## Specific information:

6. Did the district replace any school structures with new buildings during the reporting year?

Yes ○

No ◉

a. If No please go to question #7

b. If Yes please fill out the following information FOR EACH STRUCTURE that was replaced

i. Name and address of the school where structure was replaced

ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)

iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)

iv. Maximum occupancy of new structure

v. Date the new structure became occupied

| i. Name and address of the school where structure was replaced |
| --- |
| |
| ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.) |
| |
| iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.) |
| |
| iv. Maximum occupancy of new structure |
| |
| v. Date the new structure became occupied |
| |

| i. Name and address of the school where structure was replaced |
| --- |
| |
| ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.) |
| |
| iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.) |
| |
| iv. Maximum occupancy of new structure |
| |
| v. Date the new structure became occupied |
| |

| i. Name and address of the school where structure was replaced |
| --- |
| |
| ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.) |
| |
| iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.) |
| |
| iv. Maximum occupancy of new structure |
| |
| v. Date the new structure became occupied |
| |

**7. Did the district modify an existing school building in a manner that may affect the seismic risk category of a school?**

Yes ◉

No ○

**a. If No you are finished - Please go to the end of the form for submittal instructions**

**b. If Yes please fill out the following information FOR EACH STRUCTURE that was modified**

**i. Name and address of the school where structure was modified**

Alice Ott Middle School
12500 SE Ramona, Portland, OR

**ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)**

portions of main building

**iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)**

Roofing diaphragm and structural upgrades in attic space

**iv. Date the structure was re-occupied after modification**

2008

**c. Optional - submit a copy of the seismic rehabilitation or structural engineering report**

**Please attach to email when you submit this form.**

**d. Optional - cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)**

| |
|---|
| **i. Name and address of the school where structure was modified** |
| Lincoln Park Elementary School<br>13200 SE Lincoln St.<br>Portland, OR |
| **ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)** |
| main building |
| **iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)** |
| roof diaphragm strapping/sheathing and anchor to load bearing walls |
| **iv. Date the structure was re-occupied after modification** |
| 2009 |
| **c. Optional – submit a copy of the seismic rehabilitation or structural engineering report** |
| **Please attach to email when you submit this form.** |
| **d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)** |
| |

| |
|---|
| **i. Name and address of the school where structure was modified** |
| Gilbert Heights<br>12839 SE Holgate St.<br>Portland, OR |
| **ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)** |
| main building |
| **iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)** |
| roof diaphragm strapping/sheathing and anchor to load bearing walls |
| **iv. Date the structure was re-occupied after modification** |
| 2008 |
| **c. Optional – submit a copy of the seismic rehabilitation or structural engineering report** |
| **Please attach to email when you submit this form.** |
| **d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)** |
| |

| |
|---|
| **i. Name and address of the school where structure was modified** |
| Menlo Park Elementary School<br>12900 NE Glisan St.<br>Portland, OR |
| **ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)** |
| north classroom wing and gymnasium |
| **iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)** |
| roof diaphragm strapping/sheathing and anchor to load bearing walls; main entry walls reinforced |
| **iv. Date the structure was re-occupied after modification** |
| 2009 |
| **c. Optional - submit a copy of the seismic rehabilitation or structural engineering report** |
| **Please attach to email when you submit this form.** |
| **d. Optional - cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)** |
| |
| **Please submit your completed report to:**<br>**seismic.feedback@dogami.state.or.us**<br><br>**Thank you for your cooperation.** |