# Oregon Schools Seismic Feedback Form General information: 1. Date of submittal August 21, 2012 2. County Malheur 3. School district or special education district Malheur ESD 4. Name and title of person submitting report Dr. Stephen W. Phillips 5. Year for reporting - Please submit separate forms for each year of reporting 2008-2012

Specific information:
6. Did the district replace any school structures with new buildings during the reporting year?
Yes •
No O
a. If No please go to question #7
b. If Yes please fill out the following information FOR EACH STRUCTURE that was replaced
i. Name and address of the school where structure was replaced
Malheur Education Center (MEC) 575 Thunderegg Blvd. Nyssa, OR 97913
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
Not a replacement- a brand new building
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
Wood frame
iv. Maximum occupancy of new structure
65
v. Date the new structure became occupied
August 2008

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main
building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

i. Name and address of the school where structure was replaced	
ii. Exact structure or structures that were replaced (for example, gymnasium, mai building, etc.)	n
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc	.)
iv. Maximum occupancy of new structure	
v. Date the new structure became occupied	

i. Name and address of the school where structure was replaced
1. Haine and address of the school where structure was represent
ii. Exact structure or structures that were replaced (for example, gymnasium, main
building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

7. Did the district modify an existing school building in a manner that may affect the seismic risk category of a school?
Yes 🔘
No ①
a. If No you are finished – Please go to the end of the form for submittal instructions
b. If Yes please fill out the following information FOR EACH STRUCTURE that was modified
i. Name and address of the school where structure was modified
ii. Exact structure or structures that were modified (for example, gymnasium, main
building, etc.)
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
iv. Date the structure was re-occupied after modification
c. Optional - submit a copy of the seismic rehabilitation or structural engineering
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
building, etc.)
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
Termoreament, early
iv. Date the structure was re-occupied after modification
1v. Date the structure was re-occupied after mounteactors
c. Optional – submit a copy of the seismic rehabilitation or structural engineering
report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through
Seismic Rehabilitation Grant Program, local school bond, etc.)
L

i. Name and address of the school where structure was modified
1. Wallie and address of the sensor where strategy was mountain
ii. Exact structure or structures that were modified (for example, gymnasium, main
building, etc.)
building, etc.)
iii. Type of modification to the building (for example, awnings anchored, structural
reinforcement, etc.)
iv. Date the structure was re-occupied after modification
17. Duce the Structure was to occupied after mountained.
Ontinual autority and a server false action is repositive to or expression or expressi
c. Optional – submit a copy of the seismic rehabilitation or structural engineering
report
Please attach to email when you submit this form.
d. Optional - cost and method of seismic rehabilitation funding (grant through
l ''
Seismic Rehabilitation Grant Program, local school bond, etc.)