Oregon Schools Seismic Feedback Form

General information:

1. Date of submittal

8/24/2012

2. County

Multnomah

3. School district or special education district

Portland Public Schools, SD 1J

4. Name and title of person submitting report

Jen Sohm, Project Manager

5. Year for reporting - Please submit separate forms for each year of reporting

2009

Specific information:

6. Did the district replace any school structures with new buildings during the reporting year?

Yes ○

No ◉

a. If No please go to question #7

b. If Yes please fill out the following information FOR EACH STRUCTURE that was replaced

i. Name and address of the school where structure was replaced

ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)

iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)

iv. Maximum occupancy of new structure

v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

i. Name and address of the school where structure was replaced
ii. Exact structure or structures that were replaced (for example, gymnasium, main building, etc.)
iii. Type of replacement building (for example, tilt-up, masonry, wood frame, etc.)
iv. Maximum occupancy of new structure
v. Date the new structure became occupied

7. Did the district modify an existing school building in a manner that may affect the seismic risk category of a school?

Yes ◉

No ○

a. If No you are finished - Please go to the end of the form for submittal instructions

b. If Yes please fill out the following information FOR EACH STRUCTURE that was modified

i. Name and address of the school where structure was modified

Lane Middle School
7200 SE 60th Avenue
Portland, OR 97206

ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)

1949 South wing, 1955 North wing

iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)

strengthen roof diaphragm and roof to wall connections

iv. Date the structure was re-occupied after modification

September 2009

c. Optional - submit a copy of the seismic rehabilitation or structural engineering report

Please attach to email when you submit this form.

d. Optional - cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Columbia Transportation & Pioneer High School 716 NE Marine Drive Portland, OR
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
Original 1937 school building, 1927 gym and 1949 addition, 1950 classroom sector at east, 1956 addition, 1959 former cafeteria and kitchen (current classroom use)
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
new plywood roof diaphragm and improve roof to wall connections
iv. Date the structure was re-occupied after modification
September 2009
c. Optional - submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional - cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Lent School 5105 SE 97th Avenue Portland, OR
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
All sectors except Multipurpose Room and classroom wing immediately north of the Multipurpose (these areas received lateral improvements in 2003)
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
strengthen roof diaphragm and connections to walls
iv. Date the structure was re-occupied after modification
September 2009
c. Optional – submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)

i. Name and address of the school where structure was modified
Scott School 6700 NE Prescott Portland, OR
ii. Exact structure or structures that were modified (for example, gymnasium, main building, etc.)
All sectors of facility with the exception of the Playshelter at the southwest portion of the site
iii. Type of modification to the building (for example, awnings anchored, structural reinforcement, etc.)
strengthen roof diaphragm and connect roof to walls
iv. Date the structure was re-occupied after modification
September 2009
c. Optional – submit a copy of the seismic rehabilitation or structural engineering report
Please attach to email when you submit this form.
d. Optional – cost and method of seismic rehabilitation funding (grant through Seismic Rehabilitation Grant Program, local school bond, etc.)
Please submit your completed report to: **seismic.feedback@dogami.state.or.us** **Thank you for your cooperation.**