

Oregon Seismic Status Report - 2016



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Myrtle Point 41

County: COOS

Contact Name: Bruce Shull

Contact Email: bshull@mpsd.k12.or.us

Structures Replaced? No

Name and Address: n/a

Kind of Structure: n/a

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: 714 4th Street Myrtle Point OR 97458

Kind of Structure: Part of the main building and gymnasium

Type of Modification:

Gymnasium Roofing system replaced and trusses upgraded and wall connections strengthened. Part of Main building (8 classrooms connected to gym) roofing system upgraded, shear walls on both levels, windows w/safety glass.

Date Re-occupied:

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab: required for seismic.

Method of Funding:

\$2 Million bond measure combined with a 1.5 Million dollar Seismic grant from ODE.

Notes: