

Oregon Seismic Status Report - 2016



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Portland 1J

County: MULTNOMAH

Contact Name: Mike Kwaske

Contact Email: mkwaske@heery.com

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Abernethy Elementary School 2421 SE Orange Ave. Portland, OR 97214

Kind of Structure: Seismic repair of roof, and bracing of existing hollow clay tile (HCT) corridor walls.

Type of Modification:

1. Seismic strengthening of the connection between the roof diaphragm and the exterior walls.
- . Bracing of parapets over entries.
- . Bracing of internal clay tile walls in the corridors.

Date Re-occupied:

Optional:


Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

Oregon Seismic Status Report - 2016



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Portland 1J

County: MULTNOMAH

Contact Name: Mike Kwaske

Contact Email: mkwaske@heery.com

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Cleveland High School 3400 SE 26th Ave. Portland, OR 97202

Kind of Structure: Seismic repair of roof.

Type of Modification:

1. Seismic strengthening of the connection between the roof diaphragms and the exterior walls.
- . Some roof decks were replaced.
- . Some roof decks received plywood to strengthen the roof diaphragms.

Date Re-occupied:

Optional:


Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

Oregon Seismic Status Report - 2016



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Portland 1J

County: MULTNOMAH

Contact Name: Mike Kwaske

Contact Email: mkwaske@heery.com

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Jefferson High School 5210 N. Kerby Ave. Portland, OR 97217

Kind of Structure: TV Studio - South Wall

Type of Modification:

Brace the existing URM walls at the TV Studio / Old Gymnasium building. Provide structural steel bracing of the tall URM piers between the large infilled windows of the South wall.

Date Re-occupied:

Optional:


Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

Oregon Seismic Status Report - 2016



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.
This report was generated by DOGAMI from submitted data.**

School District/ESD: Portland 1J

County: MULTNOMAH

Contact Name: Mike Kwaske

Contact Email: mkwaske@heery.com

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Metropolitan Learning Center 2033 NW Glisan St. Portland, OR 97209

Kind of Structure: Seismic upgrade of hallways on all floors.

Type of Modification: Bracing of existing hollow clay tile (HCT) corridor walls.

Date Re-occupied:

Optional:


Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

Oregon Seismic Status Report - 2016



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Portland 1J

County: MULTNOMAH

Contact Name: Mike Kwaske

Contact Email: mkwaske@heery.com

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: Sellwood Middle School

Kind of Structure: Seismic repair of roof.

Type of Modification: Seismic strengthening of the connection between the roof diaphragm and the exterior walls.

Date Re-occupied:

Optional:

Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: