

## Oregon Seismic Status Report - 2017



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Cascade 5

County: MARION

Contact Name: Scott B. Pillar

Contact Email: spillar@cascade.k12.or.us

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Turner Elementary School 7800 School Av. Turner, OR 97392

Kind of Structure: Main building

Type of Modification: Full structural reinforcement following awarding of seismic grant.

Date Re-occupied:

**Optional:**

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Seismic Rehabilitation Grant Program

Notes: