

Oregon Seismic Status Report - 2017



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: David Douglas 40

County: MULTNOMAH

Contact Name: PAT KOMAR

Contact Email: PATT_KOMAR@DDSD40.ORG

Structures Replaced? No

Name and Address:

Kind of Structure:

Type of Replacement:

Max Occupancy:

Date Occupied:

Structures Modified? Yes

Name and Address: MILL PARK ELEMENTARY SCHOOL, 1900 SE 117TH AVENUE, PORTLAND, OR

Kind of Structure: CAFETERIA, KITCHEN, CROSS HALLWAY

Type of Modification: STRUCTURAL REINFORCEMENT

Date Re-occupied: 08/23/17

Optional:

Engineering Report? No *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: