


## Oregon Seismic Status Report - 2019



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Greater Albany 8J

County: LINN

Contact Name: Doug Pigman

Contact Email: DOUG.PIGMAN@ALBANYK12.OR.US

**Structures Replaced?** Yes

Name and Address: 1500 Oak Grove Drive NW, Albany, Or 97321

Kind of Structure: Whole Building

Type of Replacement: Wood Frame

Max Occupancy: 2429

Date Occupied: 09/03/19

**Structures Modified?** Yes

Name and Address: 3610 Grand Prairie SE Rd

Kind of Structure:

Type of Modification:

Date Re-occupied:

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Greater Albany 8J

County: LINN

Contact Name: Doug Pigman

Contact Email: DOUG.PIGMAN@ALBANYK12.OR.US

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Calapooia Middle School, 830 24th Ave SE, Albany, OR 97322

Kind of Structure: Throughout the building

Type of Modification: Seismic roof reinforcement  
Window Shear Walls

Date Re-occupied: 09/04/18

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



*Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.*

*This report was generated by DOGAMI from submitted data.*

**School District/ESD:** Greater Albany 8J

County: LINN

Contact Name: Doug Pigman

Contact Email: DOUG.PIGMAN@ALBANYK12.OR.US

**Structures Replaced?** No

Name and Address:

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: Memorial Middle School, 1050 Queen Ave SW, Albany, OR 97321

Kind of Structure: Throughout the building

Type of Modification: Seismic Roof Reinforcement; Window Shear Walls

Date Re-occupied: 09/03/19

**Optional:**


Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes:

# Oregon Seismic Status Report - 2019



**Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.**

**This report was generated by DOGAMI from submitted data.**

**School District/ESD:** Greater Albany 8J

County: LINN

Contact Name: Doug Pigman

Contact Email: DOUG.PIGMAN@ALBANYK12.OR.US

**Structures Replaced?** No

Name and Address: 3610 Grand Prairie SE Rd

Kind of Structure:

Type of  
Replacement:

Max Occupancy:

Date Occupied:

**Structures Modified?** Yes

Name and Address: North Albany Middle School, 1205 North Albany Road, Albany, OR 97321

Kind of Structure: Throughout building

Type of Modification: Seismic Roof Reinforcement; Window Shear Walls

Date Re-occupied: 09/03/19

**Optional:**

Engineering Report?  *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: