

Oregon Seismic Status Report - 2019



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: McMinnville 40

County: YAMHILL

Contact Name: PETER KEENAN

Contact Email: pkeenan@msd.k12.or.us

Structures Replaced? Yes

Name and Address: McMinnville High School 615 N.E. 15th St., McMinnville , OR 97128

Kind of Structure: Removed middle third of existing one story structure housing gyms ,classrooms , offices and library and rebuilt two story structure replacing what was removed but increasing 45,000 square feet

Type of Replacement: CMU block and steel framing with seismic elements built into new structure

Max Occupancy: 2500

Date Occupied: 09/03/19

Structures Modified? No

Name and Address:

Kind of Structure:

Type of Modification:

Date Re-occupied:

Optional:

Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding: Local school bond

Notes: