

Oregon Seismic Status Report - 2019



Oregon law requires school districts and education service districts to provide DOGAMI with notice of construction projects that may affect a school's seismic risk.

This report was generated by DOGAMI from submitted data.

School District/ESD: Mt Angel 91

County: MARION

Contact Name: Grant Henderson

Contact Email: Henderson_Grant@mtangel.k12.or.us

Structures Replaced? Yes

Name and Address: 890E Marquam St

Kind of Structure: CTE Wood shop building addition

Type of Replacement: Wood frame

Max Occupancy: 23

Date Occupied: 06/06/19

Structures Modified? No

Name and Address: 890E Marquam St

Kind of Structure:

Type of Modification:

Date Re-occupied:

Optional:

Engineering Report? *If yes, attachments are appended to this report.*

Cost of Rehab:

Method of Funding:

Notes: